

BRITISH PARACHUTE ASSOCIATION  
KIMBERLEY HOUSE  
47 VAUGHAN WAY  
LEICESTER  
LE1 4SG

---

BRITISH PARACHUTE ASSOCIATION

SAFETY NOTICE

1. This reserve could not be pulled.
2. Cumulative factors were as follows:
  - .1 Side flaps closed last.
  - .2 Nylon cones extended to accommodate (1)
  - .3 Excessive cable slack to accommodate (2)
  - .4 Acute cable housing angle completes the picture.
3. No pre-flight pin check was carried out.
4. All CCI's are to check for similar assemblies.
5. All jumpers to note that pin checks are mandatory (BSRs 8.3.e). Make sure they are carried out.

Doug Peacock  
National Coach & Safety  
Officer

2 July 1981

Distribution

Chairman STC  
Chairman BPA  
All Clubs  
File