



SAFETY INFORMATION

4/95

SOLDERED RESERVE PINS

Subject

Reserve pins that are soldered and attached to the RSL lanyard.

Background

After landing a reserve canopy on a Tandem Vector rig it was noted that the reserve pin had broken at the soldered point. This incident is being investigated by the manufacturer.

Note

A new type of pin is available that has been cast instead of soldered.

Any queries please contact the BPA Office.

Allan Hewitt
Chairman Riggers Committee

29th September 1995

Distribution

CCI's
Council
Riggers
STC Mailing
Sport Parachutist
File