



# SAFETY INFORMATION

6/89

## G.Q. SECURITY AND PIONEER RESERVE CANOPIES

Following the BTTG Test Report (11/1231) the Riggers Committee have decided to lift the grounding of G.Q. Security and Pioneer reserve canopies that have failed the bromocresol test provided that:

- a) Remedial action is carried out according to the 'National' Service Bulletin of 24th March 1989.
- b) In accordance with the practice used in the G.Q. remedial programme, two rows of overstitching are incorporated into the existing main seam stitching which is in contact with the new fabric.

The above action has been recommended because no further contact has been possible with the original manufacturers.

Tony Knight  
Chairman Safety and Training Committee

16th June 1989

### DISTRIBUTION

All CCIs  
All Advanced Riggers