

BRITISH PARACHUTE ASSOCIATION
5 Wharf Way
Glen Parva
Leicester
LE2 9TF

SN 1/89

S A F E T Y N O T I C E

There has been a potentially fatal incident arising from the failure of the 4 line release steering system on a Guardian 26' Lopo canopy.

Information is being sought from the manufacturers regarding this problem. In the meantime information regarding modifications should be sought from the BPA or TSE but the system should not be used until further information has been obtained.

Tony Knight
Chairman Safety & Training
Committee

Distribution

Chairman STC
Chairman BPA
All Clubs
CCI's
All Riggers