

BRITISH PARACHUTE ASSOCIATION
Kimberley House
47 Vaughan Way
LEICESTER
LE1 4SG

BRITISH PARACHUTE ASSOCIATION

SAFETY NOTICE

Because of the continuing incidents of non-stainless steel Ripcord Pins rusting and jamming in nylon loops. From 1st July 1983, Piano Wire Type Ripcord Pins are no longer to be used.

Tony Butler
JOINT NATIONAL COACH &
SAFETY OFFICER

7th February 1983

Distribution

Chairman STC
CCI's
Clubs
Advanced Riggers
File