



SAFETY NOTICE

1/90

ACID MESH PROBLEM

This Safety Notice is issued to draw to the attention of all those who pack reserves with mesh in them the fact that the Acid Mesh Problem has not gone away and that it is imperative that the proper servicing and inspection procedures are carried out on these canopies.

The procedures to be carried out when dealing with these canopies is laid out in the following Safety Information Sheets:

<u>No.</u>	<u>Issue Date</u>	<u>Issued By</u>	<u>Reference</u>
02/89	14 Feb 89	Chairman STC	GQ Parachutes Ltd -STC Service Bulletin reference Acid Mesh rectification Programme.
04/89	24 Apr 89	JNCSO for	National Parachute Industries - Service bulletin Reserves and Pilotchutes.

Anyone who does not understand these procedures or has questions should contact the JNCSOs.

Mick Thurman
Chairman Riggers Committee

27th April 1990